

Air Education and Training Command

Sustaining the Combat Capability of America's Air Force



Former Lowry Training Annex Air Force Site Fieldwork Update Restoration Advisory Board

U.S. AIR FORCE

Jerry Hodgson
28 November 2007


Integrity - Service - Excellence



Fieldwork Update



- Ongoing “Map-and-Dig” munitions response utilizing digital geophysical mapping:
- Addressing the area between the FLTA EOD Circle and the Navy/DRI sites
- Low density area comprised of ~460 acres
- Map-and-Dig response activities complete in the northern area (145 acres)
- Geophysical mapping of the southern area is complete (315 acres)
- Anomaly reacquisition and removals are ongoing in southern area



2



Fieldwork Update



- ~ 300 grids completed since last RAB meeting
- 50 live items found to date within the East Extension Area
- 20 demolition shots performed since last RAB meeting:
 - Bomb M50 4 Lb Incendiary
 - Bomb M52 2 Lb Incendiary
 - Booster Cup
 - Burster Tube
 - Igniter M15
 - Projectile 20mm
 - Bomb M47A2 100 Lb Incendiary
 - Grenade Smoke A8
 - Cartridge Photoflash
 - Signal Illuminating Aircraft

3



Fieldwork Update



- Summary of items recovered since last RAB meeting:

| MUNITION | QUANTITY |
|-------------------------------|-------------------|
| OE Scrap | 2,801 (pounds) |
| Small Arms | 176 |
| Bomb M74 10 Lb Incendiary | 150 |
| Bomb M50 4 lb Incendiary | 48 |
| Bomb MK23 3 Lb Practice | 36 |
| Projectile 20mm | 16 |
| Misc. Fuzes | 15 |
| Rocket 2.25" | 11 |
| Burster Tube | 10 |
| Bomb M69 6 Lb Incendiary | 3 |
| Projectile 37mm/37mm TP | 2 |
| Spotting Charge M38 | 2 |
| Warhead Rocket 2.75" Practice | 2 |
| Cartridge Photoflash | 1 |
| Booster Cup | 1 |
| Bomb Photoflash | 1 |
| Bomb M38 100 Lb Practice | 1 |

4



Fieldwork Update



- Over 30 grids have required unanticipated “Mag-and-Dig” munitions response activities:
 - Areas not accessible for geophysical mapping (gullies and surface debris areas)
 - Disposal trench within the eastern portion of the site



Excavation of former disposal trench

5



Fieldwork Update



Debris from former disposal trench



6



Fieldwork Update



Debris from former disposal trench




7



Remaining Activities



- Complete munitions response activities within the southern area (winter/spring 2008)
- Post-removal verification for the entire 460 acre East Extension Area (spring 2008)
- Final reporting (late 2008)



Sustaining the Combat Capability of America's Air Force



Integrity - Service - Excellence